


20. WIRING DIAGRAMS



| | | | |
|---|--------|----|-------------|
| W | BLACK | W | WHITE |
| Y | YELLOW | D | DRAB |
| B | BLUE | L | LIGHT BLUE |
| G | GREEN | L | LIGHT GREEN |
| R | RED | P | PINK |
| U | VIOLET | GR | GRAY |

0030Z-MCF-6700
0030Z-MCF-7700

